

# Captain of Ports Department

Government of Goa  
Dayanand Bandopkar Road,  
Panaji - Goa - 403001, India.

Phone Nos: +91(0832) 2225070/2426109  
Website: [www.ports.goa.gov.in](http://www.ports.goa.gov.in)  
Shipping - Phone Nos.: +91(0832) 2420579/2420580

Fax: +91(0832) 2421483  
E-mail: [cpt-port.goa@nic.in](mailto:cpt-port.goa@nic.in)  
Fax: +91(0832) 2420582

No. C - 23011/SPG/2089

Dated: - 13/09/2021.

## NOTICE TO MARINERS (Goa Inland Waters)

1. It is hereby notified that until further orders, the Aguada Bar is declared open for all water-borne traffic with effect from 0000 hours of 16<sup>th</sup> September 2021.
2. It is also notified that the Lighthouses of Campal, Tejo Front, Tejo Rear, Reis Magos, Penha de Franca, and Aguada Beacon will start functioning from the above date with usual Characteristics.
3. It is further notified that the Old Aguada Lighthouse located inside the Fort exhibits a fixed white light on the outer wall of the Old Aguada Lighthouse structure visible over an area of 153° (Degrees) equidispersed on either side of the line traversing the Old Aguada Lighthouse structure and the Aguada Beacon at the foot of the hill. Mariners are particularly warned to keep well to the seaward of such line giving wide berth to the shoals of outer patches, Amee shoals and Sunchi Reefs.
4. Mariners should particularly be aware that the line traversing the new Aguada Lighthouse and the Aguada Beacon is NOT repeat NOT a clearing line for the above mentioned shoals and under no circumstances should Mariners navigate along such line.
5. It is also notified that navigation through the Cumbarjua Canal under the Banastarim Bridge is totally banned except with prior permission of the Captain of Ports, Panaji.
6. A Black and Yellow Buoy flashing 'QUICK WHITE' every 1.0 seconds (QW-0.2s+0.8s) is laid to mark the shallow patch namely 'REIS SAND' opposite Reis Magos Lighthouse, at geographical position 15° 29' 57" N and 73° 48' 52" E approximately.
7. Vessels proceeding to seaward should keep the above referred Black and Yellow Buoy to their port side and vessels entering Panaji Port should keep the Buoy to their starboard side by keeping a safe distance from the Buoy.
8. Mariners are warned that the Buoy may drift out of its position. They should therefore navigate the area with **UTMOST CAUTION AS REQUIRED BY PRUDENT SEAMANSHIP**, go slow, scan the area and then proceed.
9. OWNERS/MARINERS are advised to inform the Captain of Ports immediately in the case of Buoy is drifted.

Cont...2/-

10. Mariners are warned that the weather may become rough at any time and should therefore be cautious to cross the Aguada Bar in such conditions.

11. It is also notified that the navigation under the Mandovi Bridges and the Zuari Bridges will be permitted as per the following instructions/directives;

(i) All Outbound vessels should navigate the area with MINIMUM SPEED passing through spans comprising of Piers P 13 & P14 of New Mandovi Bridge and Piers P 8 & P 9 of Old Mandovi Bridge.

These Piers are mounted with sign boards with RED square on white background and GREEN Triangle on white background respectively. During the night 3 green lights in vertical line one above the other will be displayed at top center of the navigable span visible in the direction of approach only.

(ii) All Inbound vessels should navigate the area with MINIMUM SPEED passing through spans comprising of Piers P 7 & P 8 of Old Mandovi Bridge and Piers P 12 & P 13 of New Mandovi Bridge.

These Piers are mounted with sign boards with RED square on white background and GREEN Triangle on white background respectively. During the night 3 Nos. green lights in vertical line one above the other will be displayed at top centre of the navigable span visible in the direction of approach only.

12. (A) A lookout man should be placed on the bow of the vessel from Campal Lighthouse to Britona and vice versa, day and night to keep a sharp watch for ferryboats buoys, vessels etc.

(B) Vessels navigating near or between the bridge piers should go at MINIMUM SPEED and should stop in half its length. DO NOT ATTEMPT to navigate under the bridge if conditions are not favourable or conducive for safe navigation.

(C) Owners are to take ABSOLUTE CAUTION to ensure that the vessels are Sea worthy in every respect viz engines, steering and manning. They are to ensure that Masters with disabilities, bad eye sight, drunkenness or any deficiency that may hamper their reflexes or efficiëncing competency should not be put on duty while navigating.


(D) Vessels navigating during spring tide should be extra cautious due to strong tidal effect cross currents which could drift the vessels on the Bridge piers, etc.

(E) In case of any doubt /poor visibility /strong currents/strong winds, vessels should not endeavour or attempt to pass under the bridges.

13. OWNERS/MARINERS ARE REQUIRED TO EXERCISE EXTREME CAUTION WHILE NAVIGATING THROUGH BRIDGES. VIOLATIONS OF ABOVE INSTRUCTIONS WILL BE DEALT WITH SEVERELY UNDER RULES IN FORCE.
14. CROSSING OR OVERTAKING OF VESSELS IN THE VICINITY OF BRIDGES IN THE RIVERS 500 METRES ON EITHER SIDE OF THE BRIDGE IS STRICTLY PROHIBITED.
15. All vessels plying through the New Konkan Railway Bridge at Daujim, across River Mandovi are required to navigate under the span with UTMOST CAUTION. The horizontal clearance is 124.2 metres. And the vertical clearance is 12.9 metres.
16. All Owners /Masters/Serangs of the Barges and other inland vessels should adhere to the INLAND VESSELS (MOTOR) NAVIGATION RULES, 1968. Further to this all Owners/Masters/Serangs of the Barges and other Inland Vessels are hereby notified to be thoroughly conversant with the existing vertical and horizontal clearance of all the Bridges in the Inland Waterways of Goa. It is pointed out that there are numerous passenger ferry crossing in the Inland Waterways of Goa. EXTREME CAUTION will have to be exercised when navigating at the vicinity of the passenger ferry routes and the bridges(s), pillars and avoid collisions. Passengers Ferry Boats will have the right of way, others to keep clear. Any damage, or harm, or any other minor occurrence as a result of these commercial activities will have to be compensated to the Government.
17. All Owners/Masters/Serangs of the vessels should strictly and scrupulously adhere to the above instructions and exercise utmost care and utmost caution while approaching/negotiating the bridges and proceed with a speed just sufficient for a steering and stopping the vessels within their own length.
18. Attention is also drawn to Circular No. C-23011/SPG/813 dated 23.03.1992, for compliance.
19. Vessels will be permitted to operate West of Aguada Bay within Panaji Port Limits and are advised to exercise due caution as the weather is liable to deteriorate without warning. Vessels loading West of Aguada Bay will be permitted to load upto their mark. All ships calling at Panaji Port are cautioned to remain anchored firmly within the limits of the Panaji Port and should not create any sort of pollution.
20. It is hereby cautioned that the minimum depth over the Aguada Bar is 2.7 Metres below the chart datum on the mouth of river Mandovi at geographical position Latitudes 15° 28' 52" N and Longitude 73° 47' 51" E approximately on main transit line.

21. Masters /Serangs of all vessels exceeding draught of 2.6 Metres are hereby WARNED NOT TO CROSS THROUGH THE AGUADA SAND BAR DURING LOW WATER PERIOD, and are advised to cross through the Aguada Sand Bar only during high water period, with utmost care and caution by assessing the situation.
22. Masters/Serangs/Owners violating the above instructions shall be severely dealt with under the Rules and Regulation in force.

Please acknowledge receipt.

  
(Capt. James Braganza)  
Captain of Ports

Forwarded to:-

1. COP Dept. Website.
2. All Barge Owners.
3. The Goa Barge Owners Association, Vasco-da-Gama.
4. The Goa Mineral Ore Exporters Association, Panaji.
5. The Mormugao Passengers Launch Association, Mormugao - Goa.
6. The Director of River Navigation Department, Betim.
7. All Owners of Passengers Launches.
8. All India Radio, Panaji.
9. The Director of Fisheries, Panaji.
10. The Chairman, M.P.T., Mormugao - Harbour.
11. The Dy. Conservator, M.P.T. Mormugao - Harbour.
12. The Director of Information and Publicity, Panaji.
13. The Technical Superintendent, Captain of Ports Department, Panaji - Goa
14. The Hydrographic Surveyor, Captain of Ports Department, Panaji.
15. The Dy. Captain of Ports, Mormugao - Harbour.
16. The Federation of all India Sailing Vessels, Mumbai.
17. The Chief Engineer (MBP), Altinho, Panaji.
18. The Chairman Mandovi Fisherman, MKrg. Co-Op-Society Ltd., Panaji.
19. The Chief Engineer, Roads & Bridges, Altinho.
20. The Development Commissioner, Secretariat, Porvorim.
21. The Chief Secretary, Secretariat, Porvorim.
22. The Secretary Ports, Secretariat, Porvorim.
23. The Secretary, RND, Secretariat, Porvorim.
24. The Principal, Maritime School, Britona.
25. The P.S. to Hon'ble Minister for I.W.T., Secretariat, Porovim.
26. The P.S. to Governor of Goa, Raj Bhavan, Dona Paula, Goa.
27. The P.S. to Hon'ble Chief Minister, Secretariat, Porvoim.
28. The Commandant, INS Mandovi, Verem.
29. The Station Director, Doordarshan, Altinho, Panaji.
30. The Director General of Police, Panaji.
31. The Commander, Cost Guard Dist HQ, 11 2<sup>nd</sup> floor, M.P.T., Old Admn Bldg. MRH
32. The Superintendent, Customs and Central Excise, Panaji Minor Port.
33. M/s. Salgaocar Mining Ind. Ltd, Salgaocar Chamber, Margao.
34. M/s. Hiralal & Comapany, Swatantra Path, P.Box. No. 8, Vasco-da-Gama.
35. M/s. Sesa Goa Limited, Sesa Ghor, E.D.C. Complex, Panaji - Goa.
36. M/s. Damodhar Mangalji and Company, Damodar Niwas, Panaji - Goa.
37. M/s. M.M.T.C. P. Box. No. 37, Colaco Building, Swatantra Path, Vasco-da-Gama.
38. The Assistant Engineer, Konkan Railway Corporation Limited, Rawanfond - Margao.
39. M/s. Chowgule Brothers, Mormugao - Harbours.
40. The Supervisor (LHK), Panaji.
41. All Goa Water Sports Owners.
42. Office Copy.